




We are ½ way through roof framing the steel you see is for the elevator penthouse and hoisting beam that will be installed in the next few weeks



The front stair case framing is complete from basement to fifth floor we are working on the rear stair case now



4th floor structural framing is complete. The steel in the picture are the supports for the elevator track system